



COMPONENTS




101




104



105




106



102



103




106


HARDWARE

A M6 x 75 4 pcs.	B M6 x 65 4 pcs.	C M6 x 20 4 pcs.	D 4 x 40 4 pcs.
E 8 pcs.	F 1 pc.	G 1 pc.	

TOOLS REQUIRED





flat head screwdriver




screwdriver


STEP 1




STEP 2



STEP 3



STEP 4



**OPAL COUNTER HEIGHT
TABLE**

63250

Assembly Instructions

